

MARYLAND HISTORICAL TRUST  
21 STATE CIRCLE  
SHAW HOUSE  
ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET  
Individual Structure Survey Form

COUNTY: Anne Arundel		SURVEY NUMBER: AA 517	
TOWN: Annapolis		NEGATIVE FILE NUMBER:	
LOCATION: 183 Green Street		UTM REFERENCES: Zone/Easting/Northing	
COMMON NAME:		U.S.G.S. QUAD. MAP:	
FUNCTIONAL TYPE: Res Map 32 Par 292		PRESENT FORMAL NAME:	
OWNER: Historic Annapolis, Inc.		ORIGINAL FORMAL NAME:	
ADDRESS: 194 Prince George St. Annapolis, MD 21401		PRESENT USE: Vacant	
ACCESSIBILITY TO PUBLIC: Yes (X) No ( ) Restricted ( )		ORIGINAL USE: SF Res	
LEVEL OF SIGNIFICANCE: Nat. Reg. ( ) Local (X) State ( ) National (*)		ARCHITECT/ENGINEER:	
GENERAL DESCRIPTION:		BUILDER/CONTRACTOR:	
Structural System		PHYSICAL CONDITION OF STRUCTURE:	
1. Foundation: Stone ( ) Brick (X) Concrete ( ) Concrete Block ( )		Excellent ( ) Good ( )	
2. Wall Structure		Fair (X) Poor: ( )	
A. Wood Frame: Post and Beam ( ) Balloon (X)		THEME:	
B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )		STYLE: Colonial	
C. Iron ( ) D. Steel ( ) E. Other:		DATE BUILT: c1740	
3. Wall Covering: Clapboard (X) Board and Batten ( ) Wood Shingle ( ) Shiplap ( )			
Novelty ( ) Stucco ( ) Sheet Metal ( ) Aluminum ( ) Asphalt Shingle ( )			
Brick Veneer (X) Stone Veneer ( ) Asbestos Shingle ( )			
Bonding Pattern: Flemish		Other:	
4. Roof Structure			
A. Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )			
B. Other:			
5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (X)			
Built Up ( ) Rolled ( ) Tile ( ) Other:			
6. Engineering Structure:			
7. Other:			
Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers (X) Chimneys (X) Sheds ( ) Ells (X)			
Wings ( ) Other:			
Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )			
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( ) With False Front ( )			
Other:			
Number of Stories: 2 1/2			
Number of Bays: 2 x 1		Entrance Location: Right	
Approximate Dimensions: 20 x 28			
THREAT TO STRUCTURE: No Threat (X) Zoning ( ) Roads ( ) Development ( ) Deterioration ( ) Alteration ( ) Other:		LOCAL ATTITUDES: Positive ( ) Negative ( ) Mixed ( ) Other:	

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

AA-517

Gabled dormer, boxed cornice, beaded weatherboards, brick end wall with chimney (new); molded window and transom lit door caps; entrance porch to be added-under restoration.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Very early 18thC house of architectural importance as a type, under restoration. Sits back on landscaped lot. Important to streetscape. Was Blacksmith's House.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane( ) Woodland( ) Scattered Buildings( )  
 Moderately Built Up(✓) Densely-Built Up( )  
 Residential( ) Commercial( )  
 Agricultural( ) Industrial( )  
 Roadside Strip Development( )  
 Other:

RECORDED BY:

Russell Wright

ORGANIZATION:

Historic Annapolis, Inc

DATE RECORDED:


Aug. 1983

# Easement


AA-517

020517 2104

Form 10-445  
(5/62)

1. STATE <u>Annapolis, Maryland</u> COUNTY _____ TOWN _____ VICINITY _____ STREET NO. <u>183 Green Street</u>		HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY	
ORIGINAL OWNER _____ ORIGINAL USE <u>residence</u> PRESENT OWNER <u>Dorothy Strickland</u> PRESENT USE <u>residence (vacant)</u> WALL CONSTRUCTION <u>brick/clapboard</u> NO. OF STORIES <u>two plus dormer attic</u>		2. NAME <u>Brewer House</u>  DATE OR PERIOD <u>c. 1740</u> STYLE <u>Georgian</u> ARCHITECT _____ BUILDER _____	
4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION		3. FOR LIBRARY OF CONGRESS USE	
OPEN TO PUBLIC <u>no</u>		Set back from Green Street and hidden by massive foliage is an outstanding example of colonial American architecture. The house is almost totally unaltered except for 1st storey windows in front and porch addition. Three walls are wide, overlapping clapboard, the other, an end wall in English bond brick, including a massive chimney. The roof is of steep pitch with a 6/6 dormer on each side. There is a simple wood cornice. Three 2nd storey front windows are 6/6. Rear of house is very fine with original window sash, 6/6 on 2nd storey, 9/6 on 1st storey. House is raised up on c. 3' brick base. House has good deal of land for town house. Exterior restoration would be minimal and age, historical associations, and architectural significance make its preservation and maintenance an absolute must! (Also known as Iron Master's House.)	
5. PHYSICAL CONDITION OF STRUCTURE			
good		6. LOCATION MAP (Plan Optional)	
7. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.  <u>Historic Annapolis, Inc.</u> <u>Orlando Ridout IV</u>  <u>Connection H.A. Inc 18767</u>		8. NAME, ADDRESS AND TITLE OF RECORDER  <u>William D. Morgan</u> <u>Columbia University</u> <u>New York City</u>  DATE OF RECORD <u>July 19, 1967</u>	

SUPPLEMENTAL INFORMATION AND PHOTO CAPS MAY BE ADDED ON SHEET OF SAME SIZE





183 Green

AA 517

Annapolis, Anne Arundel County

Russell Wright July, 1982

Maryland Historical Trust,

Annapolis, Maryland

SE Elevation/camera facing NW

183 Green



AA-517

905  
(  
PHOTOGRAPH BY  
WILLIAM D. MORGAN

front 183 Green St.  
JUN 19 1964